## Motor Vehicle Information Report



### **Vehicle Description**

VIN	2T2ZK1BA7AC011500	Tank	19.20
Year	2010	City MPG	18
Make	Lexus	Highway MPG	25
Model	RX 350	Anti-lock Brakes	4-Wheel ABS
Manufactured In	CANADA	Steering Type	amp; Pinion;Rack &
Trim Level	front-wheel drive	Front Brake Type	Disc
Body Style	SPORT UTILITY 4-DR	Rear Brake Type	Disc
Engine Type	3.5L V6 DOHC 24V	Tires	235/60R18
Transmission	5A OD;5-Speed Automatic Overdrive	Power Door Locks	Std
Driveline	front-wheel drive	Vehicle Anti-Theft	Std

4WD/AWD

# SUMMARY

## Information from VIN as of 02/19/2025 15:29

\* The content of the report may be materially updated following the report date.

2T2ZK1BA7AC011500 11/02/2009

Current Title Record	1	
Historical Title Record	1	
Title Brand Records	0	
Junk and Salvage Records	0	
Insurer "Total loss" Records	0	
Recall Record	1	

### Title Information Last Title on record with NMVTIS

# SARKANSAS TITLE

AR

VIN		2 <b>T2ZK</b>	1BA7AC011500	
Title Issue Date	е	08/14/2	2014	
Odometer		10 M		
Please note: The odometer reading provided is as of the titling date and does not represent the current odometer reading.				
1 previous title found				
State	VIN	Issued On	Odometer	DMV Link

10 M

- If you would like additional information regarding a vehicle title, click here for contact information
- Please note: The odometer reading provided is as of the titling date and does not represent the current odometer reading.

#### Title Brand Information 0 Brands found on this VIN

• A "brand" is recorded on a vehicle's title if it was ever junked, salvaged, rebuilt, or flooded, etc. There are many different types of brands. (A complete list of all Brand Definitions is included in this report.)

We have checked the following brand **categories** in the VIN database, and found no evidence that this vehicle has been branded:

- Salvaged/Junked/Totaled
- Flood Damaged
- Commercial Use
- Odometer Issues
- Prior Theft

- Rebuilt/Reconstructed/Repaired
- Damaged
- Fire/Hail
- Cash for Clunkers

(A complete list of all Brand Definitions is included in this report)

### Junk and Salvage Information

#### **Explanatory** Note:

If this VIN has a record in the **Junk/Salvage or Insurance information** then the business that submitted the VIN to NMVTIS deemed the vehicle to be either a *junk, salvage, or in the case of an insurer, a total loss.* The information in the **DISPOSITION** field in the Junk/Salvage section denotes what has happened to the VIN (i.e., vehicle) since it came into the possession of the business.

**NOTE:** No Junk/Salvage information was found in the **VIN** records, for this vehicle. However, most consumer groups highly recommend that you have any used or repaired vehicle inspected by a qualified technician that is independent of the seller.

### **Insurer "Total Loss" Information**


#### No Information Found

### **Recall Information**

# RECALL

Name:	Potential Floor Mat Interference with Accelerator Pedal
VIN:	2T2ZK1BA7AC011500
Effective Date:	06/29/2012
Recall Last Date:	05/03/2023

Risk:	Toyota is recalling certain model year 2010 Lexus rx350 and rx450h vehicles, manufactured from November 28, 2008, through September 1, 2010, and model year 2008 through 2011 Toyota land cruiser vehicles manufactured from September 1, 2007, through September 5, 2011. In July 2012, Toyota filed a defect report to recall certain model year 2010 Lexus rx350 and rx450h vehicles. In November 2012, Toyota informed the agency that it was including an additional 10,565 vehicles including certain model year 2008 through 2011 Toyota land cruiser vehicles. The total number of vehicles being recalled is now 164,601. The accelerator pedal can get stuck in the wide open position due to its being trapped by an unsecured or incompatible drivers floor mat. A stuck open accelerator pedal may result in very high vehicle speeds and make it difficult to stop the vehicle, which could cause a crash, serious injury or death.
Remedy:	TOYOTA AND LEXUS WILL NOTIFY OWNERS OF AFFECTED VEHICLES AND DEALERS WILL MODIFY OR REPLACE THE ACCELERATOR PEDAL AND REPLACE ANY DRIVERS FLOOR MAT NOT SPECIFIED FOR THE VEHICLE. OWNERS OF THE LEXUS VEHICLES WERE NOTIFIED DURING AUGUST 2012. TOYOTA HAS NOT YET PROVIDED A NOTIFICATION SCHEDULE FOR THE ADDITIONAL LAND CRUISER VEHICLES. OWNERS MAY CONTACT TOYOTA CUSTOMER EXPERIENCE CENTER AT 1-800-331-4331 OR LEXUS AT 1-800-255-3987.
Risk Type:	collision
Description:	Collision Risk - Potential floor mat interference with accelerator pedal
Recall ID:	1397
NHTSID:	12V305000
OEMID:	9LG



<u>Click here</u> for a list of Title Brands.