

Motor Vehicle Information Report



Vehicle Description

VIN	5TEWN72N01Z845512	Tank	18.50
Year	2001	City MPG	17
Make	Toyota	Highway MPG	20
Model	Tacoma	Anti-lock Brakes	
Manufactured In	UNITED STATES	Steering Type	amp; Pinion;Rack &
Trim Level	Xtracab V6 4WD	Front Brake Type	Disc
Body Style	EXTENDED CAB PICKUP 2-DR	Rear Brake Type	Drum
Engine Type	3.4L V6 DOHC 24V	Tires	225/75R15
Transmission		Power Door Locks	Opt
Driveline	four-wheel drive	Vehicle Anti-Theft	Opt
4WD/AWD	Std		

SUMMARY

Information from VIN as of 11/10/2024 12:24

* The content of the report may be materially updated following the report date.

Current Title Record	1
Historical Title Record	8
Title Brand Records	0
Junk and Salvage Records	0
Insurer "Total loss" Records	0
Recall Record	1

Title Information

Last Title on record with NMVTIS

CALIFORNIA TITLE

VIN	5TEWN72N01Z845512
Title Issue Date	10/10/2023
Odometer	EXEMPT

Please note: The odometer reading provided is as of the titling date and does not represent the current odometer reading.

- If you would like additional information regarding the title from this jurisdiction, please [click here](#)

8 previous titles found

State	VIN	Issued On	Odometer	DMV Link
CA	5TEWN72N01Z845512	09/12/2023	EXEMPT	click here

OR	5TEWN72N01Z845512	07/13/2023	EXEMPT
OR	5TEWN72N01Z845512	10/14/2022	EXEMPT
NY	5TEWN72N01Z845512	07/27/2021	EXEMPT
NY	5TEWN72N01Z845512	06/24/2021	EXEMPT
NY	5TEWN72N01Z845512	06/09/2021	EXEMPT
NY	5TEWN72N01Z845512	06/15/2012	EXEMPT
NY	5TEWN72N01Z845512	09/29/2003	35,416 M

- If you would like additional information regarding a vehicle title, [click here](#) for contact information
- Please note: The odometer reading provided is as of the titling date and does not represent the current odometer reading.

Title Brand Information

0 Brands found on this VIN

- A "brand" is recorded on a vehicle's title if it was ever junked, salvaged, rebuilt, or flooded, etc. There are many different types of brands. (A complete list of all Brand Definitions is included in this report.)

We have checked the following brand **categories** in the VIN database, and found no evidence that this vehicle has been branded:

- Salvaged/Junked/Totaled
- Flood Damaged
- Commercial Use
- Odometer Issues
- Prior Theft
- Rebuilt/Reconstructed/Repaired
- Damaged
- Fire/Hail
- Cash for Clunkers

(A complete list of all Brand Definitions is included in this report)

Junk and Salvage Information

Explanatory Note:

If this VIN has a record in the **Junk/Salvage or Insurance information** then the business that submitted the VIN to NMVTIS deemed the vehicle to be either a *junk, salvage, or in the case of an insurer, a total loss*. The information in the **DISPOSITION** field in the Junk/Salvage section denotes what has happened to the VIN (i.e., vehicle) since it came into the possession of the business.

NOTE: No Junk/Salvage information was found in the **VIN** records, for this vehicle. However, most consumer groups highly recommend that you have any used or repaired vehicle inspected by a qualified technician that is independent of the seller.


Insurer "Total Loss" Information

No Information Found

Recall Information



Name:	Excessive Corrosion of Spare Tire Carrier Lift Plate *Salt States*
VIN:	5TEWN72N01Z845512
Effective Date:	11/23/2012
Recall Last Date:	09/25/2024
Risk:	<p>Toyota is recalling certain model year 2001 through 2004 tacoma light trucks manufactured from August 28, 2000, through August 27, 2004, and originally sold, or currently registered, in the following cold climate states with high road salt usage: connecticut, delaware, illinois, indiana, kentucky, maine, maryland, massachusetts, michigan, minnesota, new hampshire, new jersey, new york, ohio, pennsylvania, rhode island, vermont, virginia, west virginia, wisconsin, and the district of columbia. The spare tire in the subject vehicles is located underneath the rear of the vehicle and held by a spare tire carrier. A lift plate on the carrier is used to help raise, lower and retain the tire. During its manufacture, the lift plate may not have been sufficiently coated with anti-corrosion materials. If the plate is insufficiently coated and the vehicle is operated in cold climate regions where road salts are frequently used, road spray can reach the carrier assembly and corrode the lift plate. Corrosion of the plate could cause it to break, which could result in detachment of the spare tire from the vehicle. Detachment of the spare tire could result in a road hazard which may increase the risk of a vehicle crash. for answers to frequently asked questions, please click.</p>
Remedy:	<p>A REMEDY FOR THIS DEFECT IS CURRENTLY BEING DEVELOPED. TOYOTA WILL NOTIFY OWNERS WHEN A REMEDY PLAN HAS BEEN FINALIZED. THE RECALL IS EXPECTED TO BEGIN DURING DECEMBER 2012. OWNERS MAY CONTACT THEIR TOYOTA DEALER OR THE TOYOTA CUSTOMER EXPERIENCE CENTER AT 1-800-331-4331.</p>
Risk Type:	safety
Description:	Safety Risk - Corrosion of the spare tire carrier lift plate
Recall ID:	777
NHTSID:	12V542000
OEMID:	C0V

Recall data provided by  RecallMasters .

[Click here](#) for a list of Title Brands.