

Motor Vehicle Information Report



Vehicle Description

VIN	1HGCV1F10KA035026	Tank	
Year	2019	City MPG	
Make	Honda	Highway MPG	
Model	Accord	Anti-lock Brakes	4-Wheel ABS
Manufactured In	UNITED STATES	Steering Type	amp; Pinion;Rack &
Trim Level	LX CVT	Front Brake Type	Disc
Body Style	SEDAN 4-DR	Rear Brake Type	Disc
Engine Type	1.5L L4 DOHC 16V TURBO	Tires	225/50R17
Transmission	CVT;Continuously Variable Transmission	Power Door Locks	
Driveline	front-wheel drive	Vehicle Anti-Theft	Std

4WD/AWD

SUMMARY

Information from VIN as of 10/03/2024 12:01

* The content of the report may be materially updated following the report date.

Current Title Record	1
Historical Title Record	5
Title Brand Records	3
Junk and Salvage Records	2
Insurer "Total loss" Record	1
Recall Record	0

Title Information

Last Title on record with NMVTIS

PENNSYLVANIA TITLE

VIN	1HGCV1F10KA035026
Title Issue Date	11/02/2022
Odometer	54,000 M

Please note: The odometer reading provided is as of the titling date and does not represent the current odometer reading.

- If you would like additional information regarding the title from this jurisdiction, please [click here](#)

5 previous titles found

State	VIN	Issued On	Odometer	DMV Link
PA	1HGCV1F10KA035026	10/06/2021	29,670 M	click here

PA	1HGCV1F10KA035026	06/29/2021	29,670 M	click here
MA	1HGCV1F10KA035026	04/23/2021	29,670 M	click here
MA	1HGCV1F10KA035026	03/31/2021	8 M	click here
MA	1HGCV1F10KA035026	02/01/2019	8 M	click here

- If you would like additional information regarding a vehicle title, [click here](#) for contact information
- Please note: The odometer reading provided is as of the titling date and does not represent the current odometer reading.

Title Brand Information

3 Brands found on this VIN

- A "brand" is recorded on a vehicle's title if it was ever junked, salvaged, rebuilt, or flooded, etc. There are many different types of brands. (A complete list of all Brand Definitions is included in this report.)

Rebuilt

Branded On	06/29/2021
Branded By	PA

The vehicle, previously branded "salvage", has passed anti-theft and safety inspections, or other jurisdiction procedures, to ensure the vehicle was rebuilt to required standards. Also known as prior salvage (salvaged).

Salvage

Branded On	04/20/2021
Branded By	MA

Damage or Not Specified - Any vehicle which has been wrecked, destroyed or damaged, to the extent that the total estimated or actual cost of parts and labor to rebuild or reconstruct the vehicle to its pre-accident condition and for legal operation on roads or highways exceeds a jurisdiction-defined percentage of the retail value of the vehicle. The retail value of the vehicle is determined by a current edition of a nationally recognized compilation (to include automated data bases) of retail values.

Salvage--Damage or Not Specified also includes any vehicle to which an insurance company acquires ownership pursuant to a damage settlement, or any vehicle that the vehicle's owner may wish to designate as a salvage vehicle by obtaining a salvage title, without regard to extent of the vehicle's damage and repairs, or any vehicle for which the jurisdiction cannot distinguish the reason the vehicle was designated salvage.

Collision

Branded On	04/20/2021
Branded By	MA

Vehicle damaged by collision.

Junk and Salvage Information

Explanatory Note:

If this VIN has a record in the **Junk/Salvage or Insurance information** then the business that submitted the VIN to NMVTIS deemed the vehicle to be either a *junk, salvage, or in the case of an insurer, a total loss*. The information in the **DISPOSITION** field in the Junk/Salvage section denotes what has happened to the VIN (i.e., vehicle) since it came into the possession of the business.



JUNK AND SALVAGE OPERATOR INFORMATION

VIN:	1HGCV1F10KA035026
Date Obtained:	03/03/2021
Disposition:	SOLD
Description:	Vehicle has been sold.
Intended for export:	NO
Name of Reporting Source:	IAA
City of Reporting Source:	WESTCHESTER
State of Reporting Source:	IL
Phone Number of Reporting Source:	7084927000
Email Address of Reporting Source:	



JUNK AND SALVAGE OPERATOR INFORMATION

VIN:	1HGCV1F10KA035026
Date Obtained:	03/03/2021
Disposition:	TO BE DETERMINED
Description:	
Intended for export:	NO
Name of Reporting Source:	IAA
City of Reporting Source:	WESTCHESTER
State of Reporting Source:	IL
Phone Number of Reporting Source:	7084927000
Email Address of Reporting Source:	

- Date Obtained: The date the vehicle was designated "junk", "salvage" or a total loss by an insurance company or anyone reporting on their behalf.
- If you have questions regarding the information provided by this reporting entity, please contact them at the telephone number or email address above.

NOTE: The above record for this vehicle indicates that it has probably suffered major prior damage, although some Junk/Salvage operators may handle vehicles with little or no damage. Consumer groups highly recommend that you have any used or repaired vehicle inspected by a qualified technician that is independent of the seller.

Insurer "Total Loss" Information



INSURER OPERATOR INFORMATION

VIN:	1HGCV1F10KA035026
Date Obtained:	02/26/2021
Name of Reporting Source:	GOVERNMENT EMPLOYEES INSURANCE COMPANY
City of Reporting Source:	GETZVILLE
State of Reporting Source:	NY

Phone Number of Reporting Source:

8008413000

Email Address of Reporting Source:

VEHINQ@GEICO.COM

- Date Obtained: The date the vehicle was designated "junk", "salvage" or a total loss by an insurance company or anyone reporting on their behalf.
- If you have questions regarding the information provided by this reporting entity, please contact them at the telephone number or email address above.

NOTE: The above record for this vehicle indicates that it has probably suffered major prior damage, although some Junk/Salvage operators may handle vehicles with little or no damage. Consumer groups highly recommend that you have any used or repaired vehicle inspected by a qualified technician that is independent of the seller.

Recall Information

No Information Found

[Click here](#) for a list of Title Brands.
