Motor Vehicle Information Report



Vehicle Description

VIN	KNAGM4A77D5439501	Tank	18.50
Year	2013	City MPG	24
Make	Kia	Highway MPG	35
Model	Optima	Anti-lock Brakes	4-Wheel ABS
Manufactured In	SOUTH KOREA	Steering Type	amp; Pinion;Rack &
Trim Level	LX AT;LX MT	Front Brake Type	Disc
Body Style	SEDAN 4-DR	Rear Brake Type	Disc
Engine Type	2.4L L4 DOHC 16V	Tires	205/65R16
Transmission	6-Speed Manual;6-Speed Automatic	Power Door Locks	Std
Driveline	front-wheel drive	Vehicle Anti-Theft	Std
4WD/AWD			

DSUMMARY

Information from VIN as of 11/20/2024 16:19

* The content of the report may be materially updated following the report date.

Current Title Record	1	
Historical Title Record	2	
Title Brand Records	0	
Junk and Salvage Records	0	
Insurer "Total loss" Records	0	
Recall Record	1	

Title Information Last Title on record with NMVTIS

MISSOURI TITLE

VIN	KNAGM4A77D5439501
Title Issue Date	05/16/2024
Odometer	181,691 M

Please note: The odometer reading provided is as of the titling date and does not represent the current odometer reading.

• If you would like additional information regarding the title from this jurisdication, please click here

2 previous titl	es found			
State	VIN	Issued On	Odometer	DMV Link
KS	KNAGM4A77D5439501	05/12/2023	32,801 M	<u>click here</u>

- If you would like additional information regarding a vehicle title, click here for contact information
- Please note: The odometer reading provided is as of the titling date and does not represent the current odometer reading.

Title Brand Information 0 Brands found on this VIN

KS

• A "brand" is recorded on a vehicle's title if it was ever junked, salvaged, rebuilt, or flooded, etc. There are many different types of brands. (A complete list of all Brand Definitions is included in this report.)

We have checked the following brand **categories** in the VIN database, and found no evidence that this vehicle has been branded:

- Salvaged/Junked/Totaled
- Flood Damaged
- Commercial Use
- Odometer Issues
- Prior Theft

- Rebuilt/Reconstructed/Repaired
- Damaged
- Fire/Hail
- Cash for Clunkers

(A complete list of all Brand Definitions is included in this report)

Junk and Salvage Information

Explanatory Note:

If this VIN has a record in the **Junk/Salvage or Insurance information** then the business that submitted the VIN to NMVTIS deemed the vehicle to be either a *junk, salvage, or in the case of an insurer, a total loss*. The information in the **DISPOSITION** field in the Junk/Salvage section denotes what has happened to the VIN (i.e., vehicle) since it came into the possession of the business.

NOTE: No Junk/Salvage information was found in the **VIN** records, for this vehicle. However, most consumer groups highly recommend that you have any used or repaired vehicle inspected by a qualified technician that is independent of the seller.

Insurer "Total Loss" Information


No Information Found

Recall Information



Name:	HECU May Cause Engine Compartment Fire
VIN:	KNAGM4A77D5439501
Effective Date:	09/25/2023
Recall Last Date:	07/03/2024
Risk:	An engine compartment fire while parked or driving can increase the risk of injury.

Remedy:	DEALERS WILL REPLACE THE HECU FUSE FREE OF CHARGE.
Risk Type:	safety
Description:	HECU may experience an electrical short and cause a fire
Recall ID:	143615
NHTSID:	23V652000
OEMID:	SC284TF



<u>Click here</u> for a list of Title Brands.