Motor Vehicle Information Report



Vehicle Description

VIN	WP0AB29887U781095	Tank	16.90
Year	2007	City MPG	20
Make	Porsche	Highway MPG	27 - 28
Model	Cayman	Anti-lock Brakes	4-Wheel ABS
Manufactured In	GERMANY	Steering Type	amp; Pinion;Rack &
Trim Level	S	Front Brake Type	Disc
Body Style	COUPE 2-DR	Rear Brake Type	Disc
Engine Type	3.4L H6 DOHC 24V	Tires	235/40R18
Transmission		Power Door Locks	Std
Driveline	rear-wheel drive	Vehicle Anti-Theft	Std
4)4/D/4)4/D			

⁴WD/AWD



Information from VIN as of 09/09/2024 11:54

* The content of the report may be materially updated following the report date.

Current Title Record	1	
Historical Title Record	6	
Title Brand Records	3	
Junk and Salvage Records	2	
Insurer "Total loss" Records	0	
Recall Record	0	

Title Information

Last Title on record with NMVTIS



VIN	WP0AB29887U781095
Title Issue Date	06/22/2022
Odometer	EXEMPT

Please note: The odometer reading provided is as of the titling date and does not represent the current odometer reading.

• If you would like additional information regarding the title from this jurisdication, please click here

6 previous ti	tles found			
State	VIN	Issued On	Odometer	DMV Link
IN	WP0AB29887U781095	05/07/2022	61,627 M	<u>click here</u>

MO	WP0AB29887U781095	10/01/2021	EXEMPT	click here
MO	WP0AB29887U781095	05/23/2013	3,577 M	click here
MO	WP0AB29887U781095	01/24/2011	3,577 M	click here
MO	WP0AB29887U781095	04/01/2008	3,577 M	click here
SC	WP0AB29887U781095	06/01/2007	187 M	click here

- If you would like additional information regarding a vehicle title, <u>click here</u> for contact information
- Please note: The odometer reading provided is as of the titling date and does not represent the current odometer reading.

Title Brand Information 3 Brands found on this VIN

 A "brand" is recorded on a vehicle's title if it was ever junked, salvaged, rebuilt, or flooded, etc. There are many different types of brands. (A complete list of all Brand Definitions is included in this report.)

Rebuilt

Branded On	06/22/2022
Branded By	IL

The vehicle, previously branded "salvage", has passed anti-theft and safety inspections, or other jurisdiction procedures, to ensure the vehicle was rebuilt to required standards. Also known as prior salvage (salvaged).

Rebuilt

Branded On	05/05/2022
Branded By	IN

The vehicle, previously branded "salvage", has passed anti-theft and safety inspections, or other jurisdiction procedures, to ensure the vehicle was rebuilt to required standards. Also known as prior salvage (salvaged).

Salvage

Branded On	10/01/2021
Branded By	MO

Damage or Not Specified - Any vehicle which has been wrecked, destroyed or damaged, to the extent that the total estimated or actual cost of parts and labor to rebuild or reconstruct the vehicle to its pre-accident condition and for legal operation on roads or highways exceeds a jurisdiction-defined percentage of the retail value of the vehicle. The retail value of the vehicle is determined by a current edition of a nationally recognized compilation (to include automated data bases) of retail values.

Salvage--Damage or Not Specified also includes any vehicle to which an insurance company acquires ownership pursuant to a damage settlement, or any vehicle that the vehicle's owner may wish to designate as a salvage vehicle by obtaining a salvage title, without regard to extent of the vehicle's damage and repairs, or any vehicle for which the jurisdiction cannot distinguish the reason the vehicle was designated salvage.

Junk and Salvage Information

Explanatory Note:

If this VIN has a record in the Junk/Salvage or Insurance information then the business that submitted the VIN to NMVTIS deemed the vehicle to be either a junk, salvage, or in the case of an insurer, a total loss. The information in the **DISPOSITION** field in the Junk/Salvage section denotes what has happened to the VIN (i.e., vehicle) since it came into the possession of the business.

▲ JUNK AND SALVAGE OPERATOR INFORMATION

VIN:	WP0AB29887U781095
Date Obtained:	07/15/2021
Disposition:	SOLD
Description:	Vehicle has been sold.
Intended for export:	NO
Name of Reporting Source:	COPART INC.
City of Reporting Source:	DALLAS
State of Reporting Source:	TX
Phone Number of Reporting Source:	9723099399
Email Address of Reporting Source:	NMVTIS.REPORTING@COPART.COM

JUNK AND SALVAGE OPERATOR INFORMATION

VIN:	WP0AB29887U781095
Date Obtained:	07/15/2021
Disposition:	TO BE DETERMINED
Description:	
Intended for export:	NO
Name of Reporting Source:	COPART INC.
City of Reporting Source:	DALLAS
State of Reporting Source:	TX
Phone Number of Reporting Source:	9723099399
Email Address of Reporting Source:	NMVTIS.REPORTING@COPART.COM

- Date Obtained: The date the vehicle was designated "junk", "salvage" or a total loss by an insurance company or anyone reporting on their behalf.
- If you have questions regarding the information provided by this reporting entity, please contact them at the telephone number or email address above.

NOTE: The above record for this vehicle indicates that it has probably suffered major prior damage, although some Junk/Salvage operators may handle vehicles with little or no damage. Consumer groups highly recommend that you have any used or repaired vehicle inspected by a qualified technician that is independent of the seller.

Insurer "Total Loss" Information

No Information Found

Recall Information

No Information Found